



CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT
FOR HURRICANE & SHORE PROTECTION PROJECTS
Honolulu Engineer District
CEPOH-EC-T

Vatia04rpt-spp.doc

1. Project Name: Vatia Shore Protection Project
2. Date of Inspection: April 13, 2004
3. Inspection Personnel:

	<u>Name</u>	<u>Agency/Office</u>	<u>Telephone No.</u>
a.	Dan Meyers	CEPOH-EC-T	438-8875
b.	Jessica Hays	CEPOH-EC-T	438-1680
c.	Casey Hiraiwa	CEPOH-EC-DC	438-9625
d.	Reuben Siatu'u	DPW	(684) 633-4141

4. CEI Rating:

Due to the lack of vegetation control a thorough inspection could not be conducted (**3rd Year**). In accordance with ER 500-1-1, (dtd 30 September 2001), and based on this CEI, the Project is rated **UNSATISFACTORY**, Project Condition Code is **UNACCEPTABLE** and the project is considered **INACTIVE** in the Rehabilitation and Inspection Program.

5. Discussion:

The SPP is 630 LF. Sta. 0+00 is the beginning of the structure, located at the West-End (Main Road Side) of the project. The project has been breached by the construction of a road at the West Side of the project. It appears than no maintenance has been conducted since the last of 9 April 2002.



Overview of Vatia SPP



The major deficiencies were as follows:




- a. Sta. 0+50 Interior tieback, remove vegetation growing among interior toe stones.



- b. Sta. 0+50 - 1+35, Remove vegetation that covers structure.
- c. Sta. 2+10 a 15', The coral road through the revetment is OK.



d. Sta. 1+55, Structure not visible from +10' to toe of revetment.



e. Sta. 1+80 - Sta. 4+85, Structure not visible from +10' to toe of revetment at numerous locations.



f. Sta. 2+50, interior-side, remove debris and vegetation.



g. Sta. 4+75, Unable to inspect crest due to vegetation.



CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT
FOR HURRICANE & SHORE PROTECTION PROJECTS
Honolulu Engineer District
CEPOH-EC-T

Vatia04rpt-spp.doc



- h. Sta. 5+00, Visible for approx. 20'.
(The entire structure should be like this)



- i. Sta. 5+00 - Sta. 6+30, Remove vegetation.




2002 Photos





CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT
FOR HURRICANE & SHORE PROTECTION PROJECTS
Honolulu Engineer District
CEPOH-EC-T

Vatia04rpt-spp.doc





CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT
FOR HURRICANE & SHORE PROTECTION PROJECTS
Honolulu Engineer District
CEPOH-EC-T

Vatia04rpt-spp.doc



