



CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT
FOR HURRICANE & SHORE PROTECTION PROJECTS
Honolulu Engineer District
CEPOH-EC-T

Matafao04rpt-spp.doc

1. Project Name: Matafao Shore Protection Project

2. Date of Inspection: April 14, 2004

3. Inspection Personnel:

	<u>Name</u>	<u>Agency/Office</u>	<u>Telephone No.</u>
a.	Dan Meyers	CEPOH-EC-T	438-8875
b.	Jessica Hays	CEPOH-EC-T	438-1680
c.	Casey Hiraiwa	CEPOH-EC-DC	438-9625
d.	Reuben Siatu'u	DPW	(684) 633-4141

4. CEI Rating:

Due to the lack of vegetation control a thorough inspection could not be conducted (**3rd Year**). In accordance with ER 500-1-1, (dtd 30 September 2001), and based on this CEI, the Project is rated **UNSATISFACTORY**, Project Condition Code is **UNACCEPTABLE** and the project is considered **INACTIVE** in the Rehabilitation and Inspection Program.

5. Discussion:

The SPP is 405LF. Sta. 1+55 is the beginning of the structure, located at the East-End of the project, the entrance road to the school is at Sta. 1+55 and ends at Sta. 5+60. All discrepancies were noted and brought to the representative's attention. The major deficiencies were as follows:



a. Sta. 1+80, New fence installed (no impact on project). Unable to inspect the revetment due to heavy vegetation.



b. Sta. 1+99 thru Sta. 3+00, unable to inspect revetment crest due to heavy vegetation.



c. Sta. 2+50, Overview of Oceanside sideslope, unable to inspect approx. 25 % due to vegetation.



d. Sta. 3+00, Revetment crest, unable to inspect revetment due to heavy vegetation.



e. Sta. 5+00, Revetment crest, unable to inspect revetment due to heavy vegetation.



f. Sta. 5+35, Oceanside sideslope of revetment, unable to inspect approx. 50 % due to vegetation.



g. Sta. 5+60, End of revetment tieback, unable to inspect due to vegetation.



2002 Photos





Sta. 4+75, Overview, Remove Vines from Revetment



Sta. 5+35, Remove Woody Vegetation and Vines from Revetment



