



CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT
FOR HURRICANE & SHORE PROTECTION PROJECTS
Honolulu Engineer District
CEPOH-EC-T

Ofu02rpt-spp.doc

1. Project Name: Ofu Shore Protection Project (SPP)

2. Date of Inspection: May 22, 2002

3. Inspection Personnel:

	<u>Name</u>	<u>Agency/Office</u>	<u>Telephone No.</u>
a.	<u>Dan Meyers</u>	<u>COE</u>	<u>438-8875</u>
b.	<u>Ray Bottin</u>	<u>COE</u>	<u>(601)-634-3827</u>
c.	<u>Andy Scandlan</u>	<u>Port Administration</u>	<u>(684)-633-5281</u>

4. CEI Rating:

IAW ER 500-1-1, (dtd 30 September 2001), and based on this CEI, the Project is rated **SATISFACTORY**, Project Condition Code is **ACCEPTABLE** and the project is considered **ACTIVE**.

5. Discussion:

The SSP consist of 381LF of armor stone protection. The beginning of the project is Sta. 1+00 is located at the East-End of the project. In general the maintenance of the project was considered good. All the discrepancies that were brought to the representative's attention during the last annual inspection have been corrected. The major deficiencies were as follows:





a. Sta. 1+00 - 1+25, vegetation (vines) has established on the armor stones; herbicide and remove.



b. Sta. 1+84, Overview of stones adjacent to eastside of the project, photo for reference.



c. Sta. 1+84, Overview photo for reference.



d. Sta. 2+75, Monitor this area for movement and settling.



e. Sta. 3+00, Overview facing East, photo for reference.



f. Sta. 4+57, Overview facing East, photo for reference.



- g. Sta. 4+60 to Sta. 4+81, Remove vegetation from structure.


5. Notes and Recommendations :

Local personnel (Port Administration) were very cordial and receptive to comments and were very willing and eager to continue and improve maintenance. The focus of the maintenance required should be directed at vegetation control. Removal or herbicides are recommended in lieu of cutting.

Signed: _____
Dan Meyers, CEPOH-EC-T

Signed: _____
Jim Pennaz, P.E., Ch, CEPOH-EC-T

Project Map:





OFU AIRSTRIP, OFU ISLAND, AMERICAN SAMOA

CONDITION OF IMPROVEMENT 30 SEPTEMBER 1989

PREVIOUS PROJECTS: None.

EXISTING PROJECT: Authorized for construction on 3 April 1986 under Section 14 of the Flood Control Act of 1946, as amended. Provides for a rock revetment 381 feet long.

PROGRESS OF WORK

Completed and Under Maintenance: The project was completed in October 1986.

Work Remaining: None.

COST OF CONSTRUCTION:

<u>Completed Works:</u>	<u>New Work</u>
United States Funds	<u>\$182,500</u>
Total Costs	<u>\$182,500</u>