

**O & M INSPECTION REPORT
FOR NAVIGATION AND SHORE PROTECTION PROJECTS**

1. Project Name: Kaunakakai DDH

2. Date of Inspection: October 25, 2000

3. Inspection Personnel:

	<u>Name</u>	<u>Agency/Office</u>	<u>Telephone No.</u>
a.	<u>Dan Meyers</u>	<u>COE</u>	<u>438-8875</u>
b.	<u>James Pennaz</u>	<u>COE</u>	<u>438-8599</u>

4. Discussion:

I met with Mr. Bernard Strehler, DOT/DLNR harbormaster. The COE has only entrance channel and turning basin responsibility, no Federally owned structures. A cursory inspection was conducted of the DOT structure to determine any impact to the Federal responsibility :



I requested that the sailboat moored in the Turing Basin be relocated to the Berthing Area. Strehler said he would advise the boaters accordingly.



Overview of oceanside revetment, no deficiencies noted.



SBH side of dock facility, no deficiencies noted on revetment.

5. Conclusion:

No permanent obstructions or structures impact the Federal project. Hydrographic surveys will be performed by Portland District in FY 01.

Signed _____
Dan Meyers, CEPOH-EC-T

Signed _____
James Pennaz, Ch, CEPOH-EC-T