



---

**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT****FOR HURRICANE & SHORE PROTECTION PROJECTS****Honolulu Engineer District****CEPOH-EC-T**

---

*Saipan04rpt-spp.doc*

1. Project Name: Saipan Beach Road SPP
2. Date of Inspection: March 26, 2004
3. Inspection Personnel:

Name	Agency/Office	Telephone No.
a. Dan Meyers	CEPOH-EC-T	808-438-8875
b. Rick Oleniczak	CEPOH-EM	808-438-1981
c. Joel Hendrix	CEPOH-EM	808-438-1275
c. Mr. Henry Bautista	DPW	670-322-9436

4. Discussion:

The project provides for approximately 1,000 LF of beach sand fill and plant stabilization. Crest elevation of +10 feet MLLW with a slope of 1V on 1.5 H . It was noted that the project has been modified. The modification consisted of placing a concrete walkway on top of the beach sand fill. The walkway is not part of this project and is not eligible for rehabilitation under PL84-99. **The Project is rated SATISFACTORY and is ACCEPTABLE.** The discrepancies listed below were noted and suggestions were made to the DPW representatives.



**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Saipan04rpt-spp.doc*



- a. Sta. 0+00, Overview facing North, no action required (sand fill begins at Sta. 2+00  $\pm$  ).



- b. Sta. 1+00, no action required.



**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Saipan04rpt-spp.doc*



c. Sta. 2+00, no action required.



d. Sta. 2+75, replenish eroded sand fill.



**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Saipan04rpt-spp.doc*



e. Sta. 3+00, overview facing north, replenish eroded sand fill as needed.



f. Sta. 4+00, overview facing north.



**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Saipan04rpt-spp.doc*



- g. Sta. 6+00, Replenish eroded sand fill as needed.



- h. Sta. 8+00, no action required.




**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Saipan04rpt-spp.doc*



- i. Sta. 10+50, replenish sand fill as needed.



- j. Sta. 12+75 (approx.) End of Project.



**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**

**FOR HURRICANE & SHORE PROTECTION PROJECTS**

Honolulu Engineer District

CEPOH-EC-T

*Saipan04rpt-spp.doc*



k. Reference Photo

5. Findings/Conclusions:

IAW ER 500-1-1, ( dtd 30 September 2001 ), and based on this CEI, the Project is rated SATISFACTORY , Project Condition Code is ACCEPTABLE and the project is considered ACTIVE in the Rehabilitation and Inspection Program.

Signed: \_\_\_\_\_  
Dan Meyers, CEPOH-EC-T

Signed: \_\_\_\_\_  
James Pennaz, P.E.,CH, CEPOH-EC-T

Enclosure(s)

1. Site Plan




# CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT

## FOR HURRICANE & SHORE PROTECTION PROJECTS

Honolulu Engineer District

CEPOH-EC-T

Saipan04rpt-spp.doc





**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**

**FOR HURRICANE & SHORE PROTECTION PROJECTS**

Honolulu Engineer District  
CEPOH-EC-T

Saipan04rpt-spp.doc

